

## Two Man Class Rules – 2018

1. Can have 4" x 4" bumper welded on front with bumper skin over it.
2. 4 hood rods – 2 at core support, 2 at fire wall. All 4 can go to frame.
3. 4 rods in trunk. All can go to frame
4. 4 point cage – 2 down bars at driver's door, 2 down bars at passenger door.
5. Fix rusty floors
6. 2 extra boddy bolts allowed on each side
7. Can run radi barrel or radiator. Cannot be attached to frame
8. Sliders allowed
9. No cradles
10. Can weld motor in no further forward than crank pulley and no further back than carburetor
11. Doors can be welded