

Two Man Class Rules – 2017

1. Can have 4x4 bumper welded on front with bumper skin over it
2. 4 hood rods
 - a. 2 at core support
 - b. 2 at fire wall
 - c. All 4 can go to the frame
3. 4 rods in the trunk can go to the frame
4. 4 point cage
 - a. 2 down bars at driver's door
 - b. 2 down bars at passenger door
5. Fix rusty floors
6. 2 extra body bolts each side
7. Can run radi barrel or radiator but can't be attached to the frame
8. Sliders OK
9. No Cradles
10. Can weld motor in no further forward than crank pulley and no further back than carb
11. Doors can be welded